

PHONE:+213 21 67 96 46
FAX :+213 21 65 63 65
AFTN :DAAAYNYX
WEB : www.sia-enna.dz

ALGERIA
E.N.N. A
AERONAUTICAL INFORMATION SERVICE
ROUTE DE CHERARBA BP 70D ALGER

NOTAM SUMMARY
SERIE B
01 MAY 17

SUMMARY OF NOTAM IN FORCE

THE FOLLOWING NOTAM WERE STILL IN FORCE AT 0025 ON 01 MAY 17,
NOTAM NOT INCLUDED HAVE EITHER BEEN CANCELLED OR SUPERSEDED
BY AIP SUPPLEMENT OR INCORPORATED IN THE AIP ALGERIA.

SERIES B

B0224/17 A)DAOR B)1703010729 C)1706010800 EST
E)TWY (GOLF) EDGE LGT UNSERVICEABLE
EXC PART BETWEEN TWY (ECHO) AND (FOXTROT)

B0227/17 A)DAOV B)1703020615 C)1706020830 EST
E)SSLI RECLASSE A LA CAT 5

B0255/17 A)DAUB B)1703100812 C)1706090700 EST
E)NEW DECLARED DISTANCES:
TORA TODA ASDA LDA
RWY 13 : 2900 2900 3100 2700
RWY 31 : 2900 2900 2900 2900

B0258/17 A)DAAE B)1703120620 C)1706100730 EST
E)PRESENCE D'OBST CONSTITUE PAR GRUE
PSN: 364414N 0050443E
QDR/DIST QFU08 :033DEG/3556M
HGT: 91.60 M
ALT ON TOP:98.60 M
BALISE JOUR ET NUIT

B0265/17 A)DAUO B)1703142016 C)1706151900 EST
E)WIP ON STRIP RWY 13/31. MEN AND EQPT PRESENCE

B0266/17 A)DAUB B)1703142017 C)1706151900 EST
E)GP RWY31 FREQ 330.8 MHZ U/S DUE TO MAINT

B0284/17 A)DAUI B)1703220641 C)1706220800 EST
E)WIP (CLOSURE) AROUND AD. MEN AND EQPT PRESENCE

B0285/17 A)DATM B)1703220643 C)1706220900 EST
E)WIND DIRECTION AND VELOCITY INFO NOT AVBL

B0293/17 A)DAAV B)1703240609 C)1706250630 EST
E)ALS RWY 17 U/S

B0294/17 A)DAOI B)1703240616 C)1706210630 EST
E)FIRE FIGHTING AND RESCUE CHANGED TO CAT 7

B0302/17 A)DAUE B)1703260728 C)1706260900 EST
E)LGT RWY 10/28 U/S

B0329/17 A)DAUE B)1704010613 C)1706010700 EST
E)WANDERING DOGS ON AD

B0330/17 A)DATM B)1704011821 C)1705021805 EST
E)NEW DECLARED DISTANCES AVBL:
TORA TODA ASDA LDA
RWY 08: 2700M 2700M 2700M 2700M
RWY 26: 2700M 2700M 2800M 2700M

B0331/17 A)DAUE B)1704011825 C)1705021810 EST
E)SWY RWY 10 UNSERVICEABLE
NEW DECLARED DISTANCES:
RWY 10 :TORA TODA ASDA LDA
1800 1800 1800 1800

B0332/17 A)DAOV B)1704011831 C)1705031815 EST
E)WINDSOCK NOT LGT AT NIGHT

B0333/17 A)DAAS B)1704020735 C)1705020733 EST
E)FIRE FIGHTING AND RESCUE UPGRADED TO CAT 7

B0336/17 A)DAUE B)1704041707 C)1705041600 EST
E)WIND DIRECTION NOT AVBL

B0337/17 A)DAAE B)1704050721 C)1705050630 EST
E)WIP AT 140M RIGHT SIDE OF RCL 08

B0338/17 A)DAOR B)1704050725 C)1705050800 EST
E)TWY K CLSD DUE TO WIP.

B0340/17 A)DAUB B)1704070629 C)1706070630 EST
E)THR RWY 13 DISPLACED 200M DUE TO WIP

B0341/17 A)DAOY B)1704070632 C)1705070630 EST
E)600M FROM THR 22 NOT AVBL DUE TO WIP
NEW DECLARED DISTANCES :
RWY04/22 :TORA=TODA=ASDA=LDA=2400M

B0342/17 A)DAAP B)1704070634 C)1705070700 EST
E)WIND DIRECTION AND VELOCITY DATA NOT AVBL

B0343/17 A)DAOY B)1704070636 C)1705070700 EST
E)INSTANTANEOUS DATA OF WIND DIRECTION AND VELOCITY NOT AVBL

B0344/17 A)DAUE B)1704080612 C)1707121000 EST
E)TWY B1 EDGE LIGHTS U/S

B0345/17 A)DAUT B)1704080613 C)1707090623 EST
E)PAPI RWY 24 U/S

B0346/17 A)DAOY B)1704080613 C)1707091000 EST
E)SWY RWY 04 AND SWY RWY 22 CLSD

B0347/17 A)DAUB B)1704080614 C)1707090623 EST
E)LLZ31/ILS BI FREQ 110.9MHZ U/S

B0348/17 A)DAUB B)1704080614 C)1707090900 EST
E)PAPI RWY 13 U/S DUE TO WIP.

B0349/17 A)DAUT B)1704081721 C)1706100700 EST
E)WIP (LGT) ON RWY 06/24. MEN AND ENGINES PRESENCE.

B0350/17 A)DAOY B)1704090727 C)1706091000 EST
E)LGT RWY 04/22 AVBL ONLY ON 2400M FM THR 04

B0352/17 A)DAAS B)1704100740 C)1705100720 EST
E)CAUSE TRAVAUX
LARGEUR DE BANDE DE PISTE:
LES PREMIERES 2400M RWY 09 EST DE 300M
LES DERNIERES 500M RWY 09 EST DE 210M

B0360/17 A)DAUO B)1704120815 C)1705120800 EST
E)WIP ON MOV AREA .MEN AND ENGINES PRESENCE

B0372/17 A)DAAJ B)1704140800 C)1706140800 EST
E)SWY RWY 13 CLSD

B0375/17 A)DAOI B)1704140907 C)1705150835 EST
E)WIP (PRKG EXTENSION) AT 250M THR 08 LEFT SIDE RWY 08/26.

B0377/17 A)DAUE B)1704150634 C)1705150700 EST
E)LGT PRKG AREA U/S

B0378/17 A)DAUB B)1704150636 C)1705150800 EST
E) INSTALLATION D'UNE CENTRALE A BETON DE (02) DEUX SILOS.
-HAUTEUR HORS SOL:25M.
-ALTITUDE 77M.
PSN:344738N 0054339E
BALISE DE JOUR SEULEMENT.

B0379/17 A)DAOV B)1704150638 C)1705160750 EST
E)WIND DIRECTION AND VELOCITY NOT AVBL

B0382/17 A)DAAV B)1704160629 C)1707160830 EST
E)PAPI RWY 17 U/S

B0386/17 A)DAOF B)1704171202 C)1705160800 EST
E)LA BOUCHE D'AVITAILLEMENT DU POSTE N02 N03 N04 EN SEVICE SAUF
LA BOUCHE DU POSTE N01 U/S

B0388/17 A)DAAD B)1704180743 C)1707190800 EST
E)WIP (CONSTRUCTION OF A TEMPORARY CLOSURE SHEET)
MEN AND ENGINES PRESENCE.

B0393/17 A)DAAS B)1704190915 C)1705190800 EST
E)WIP ON RWY 09/27 STRIP

B0394/17 A)DAOR B)1704191739 C)1705192100 EST
E)LGT TWY H U/S

B0401/17 A)DAAP B)1704210906 C)1707150800 EST
E)TWY B CLSD

B0403/17 A)DAOF B)1704210909 C)1707150800 EST
E)WIP ON RWY 08L,MEN AND EQPT PRESENCE

B0404/17 A)DAAE B)1704211732 C)1705211800 EST
E)DME BJ CH42X OPR WO AUX SUPPLY

B0406/17 A)DAAS B)1704221739 C)PERM
E)VOR/DME STF FREQ 114.6MHZ/CH93X DISPLACED WITH NEW CHARACTERISTICS:

READ NEW COORDINATE 361036N0051719E INSTEAD OF
361035.10N0051923.09E
ALT: 1023,9M
PSN: 2300M OF THR RWY 09
REF AIP ALGERIA DAAS AD2.19 PAGE AD2 DAAS-6

B0407/17 A)DAOI B)1704221810 C)1705221800 EST
E)NEW TWY CONSTRUCTION LOCATED AT 480M THR 08 LEFT SIDE RWY 08/26
MEN AND EQPT PRESENCE

B0408/17 A)DAUK B)1704230830 C)1705231500 EST
E)STRAY DOGS ON MOV AREA

B0410/17 A)DATM B)1704240602 C)1706250620 EST
E)OBST MAST ERECTED
PSN :900M FROM THR RCL 26
COOR: 21 22 55 N 000 56 54E
HGT: 15M
ALT ON TOP: 412M
NIGHT LIGHTED ONLY.

B0411/17 A)DAAA B)1704240604 C)1705260700 EST
E)REF DAOF /TINDOUF
EVERY FLIGHT OF MINURSO/U.N OR OPERATING FOR UNITED NATIONS TO
ENTER ALGIERS FIR MUST BE COMPULSORY PROCEED VIA POINT "PK 40"
GEO COORD :2720N00840W FL70.
THE FLW POINTS 2739N00840W AND 2734N00840W ARE COMPLETELY WITHDRAWN

B0413/17 A)DAAD B)1704240607 C)1705240700 EST
E)RWY 04/22 CLSD DUE TO WIP
RMK :HR 0700-1600 RWY 04/22 OPEN ONLY FOR ALGERIAN AIR FORCE ACFT

B0417/17 A)DAOB B)1704250716 C)1705250800 EST
E)TWO ACFT STANDS IN FRONT OF SIGNAL AREA CLSD

B0418/17 A)DAAE B)1704250718 C)1705240900 EST
E)WIP (CLOSURE) LEFT SIDE QFU26 MARITIME FRONT DIST 110M FROM RWY
08/26
MEN AND ENGINES PRESENCE
CAUTION ADVISED

B0419/17 A)DAUT B)1704260747 C)1705260830 EST
E)APPROACH LIGHTING SYSTEM RWY 06 U/S

B0420/17 A)DAAP B)1704260750 C)1705260800 EST
E)SWY RWY 27 UNSERVICEABLE

B0421/17 A)DAAP B)1704260752 C)1705260800 EST
E)NEW DECLARED DISTANCES:
RWY09 TORA 3000 TODA 3000 ASDA 3100 LDA 3000
RWY27 TORA 3000 TODA 3000 ASDA 3000 LDA 3000

B0422/17 A)DAOR B)1704260911 C)1705301500 EST
E)WIP (RUBBER REMOVAL AND PAINTING) ON MOV AREA MEN AND EQPT
PRESENCE.

B0425/17 A)DAUE B)1704270806 C)1705270830 EST
E)TWY B2 EDGE LIGHTS U/S

B0426/17 A)DAOF B)1704270814 C)1705270900 EST
E)WIP ON RIGHT SIDE OF RWY 26R MEN AND EQPT PRESENCE

B0427/17 A)DAUE B)1704270818 C)1705270830 EST
E)ALL LGT RWY 18/36 U/S

B0428/17 A)DAOY B)1704270821 C)1705270900 EST
E)RWY 22 SHOULDERS DAMAGED DUE TO FLOOD

B0431/17 A)DATM B)1704291732 C)1705301200 EST
E)VDF (BORDJ MOKHTAR GONIO) 119.7MHZ AND 118.3MHZ(S) U/S

B0432/17 A)DAOF B)1704291732 C)1705301230 EST
E)ANEMOMETER U/S

B0433/17 A)DATM B)1704291750 C)1705291500 EST
E)FIRST 300M FROM THR 26 NOT AVBL DUE TO WIP
MEN AND EQPT PRESENCE

B0435/17 A)DAUU B)1704302300 C)1705010330
E)CAT SSLI UPGRADED TO CAT 09

SERIES B

CHECKLIST

YEAR=2017 0224 0227 0255 0258 0265 0266 0284 0285 0293 0294
0302 0329 0330 0331 0332 0333 0336 0337 0338 0340
0341 0342 0343 0344 0345 0346 0347 0348 0349 0350
0352 0360 0372 0375 0377 0378 0379 0382 0386 0388
0393 0394 0401 0403 0404 0406 0407 0408 0410 0411
0413 0417 0418 0419 0420 0421 0422 0425 0426 0427
0428 0431 0432 0433 0435

CHECKLIST OF AIP SUPPLEMENT IN FORCE
THE FOLLOWING AIP SUPPLEMENT WERE STILL IN FORCE AT 0025 ON 01 MAY 17

2016: 001
LATEST PUBLICATIONS AT 0025 ON 01 MAY 17

AIP SUPPLEMENT 003 30 SEP 16
AIP AMENDMENT 002 06 APR 17
AIRAC AIP AMENDMENT ... 001 26 NOV 15 EFFECTIVE 07 JAN 16
AIC INTERNATIONAL 0002 20 DEC 16
AIC NATIONAL

AIRAC PUBLICATION EFFECTIVE 25 MAY 17 - NIL