

PHONE:+213 21 67 96 46
FAX :+213 21 65 63 65
AFTN :DAAAYNYX
WEB : www.sia-enna.dz
E-mail : algerian.ais@sia-enna.dz

ALGERIA
E.N.N. A
AERONAUTICAL INFORMATION SERVICE
ROUTE DE CHERARBA BP 70D ALGER

NOTAM SUMMARY
SERIE B
01 APR 17

SUMMARY OF NOTAM IN FORCE

THE FOLLOWING NOTAM WERE STILL IN FORCE AT 0010 ON 01 APR 17,
NOTAM NOT INCLUDED HAVE EITHER BEEN CANCELLED OR SUPERSEDED
BY AIP SUPPLEMENT OR INCORPORATED IN THE AIP ALGERIA.

SERIES B

B0103/17 A)DAOR B)1701310900 C)PERM
E)STRAY DOGS PRESENCE ON MOV AREA

B0106/17 A)DAUE B)1702010646 C)1704020900 EST
E)WANDERING DOGS ON AD

B0148/17 A)DAOY B)1702090740 C)1704100800 EST
E)LGT RWY 04/22 AVBL ONLY ON 2400M FM THR 04

B0149/17 A)DAUB B)1702090743 C)1704080800 EST
E)THR RWY 13 DISPLACED 200M DUE TO WIP

B0189/17 A)DAAP B)1702210715 C)1704220730 EST
E)TWY B CLSD.

B0200/17 A)DATM B)1702240652 C)1704250620 EST
E)OBST MAST ERECTED
PSN :900M FROM THR RCL 26
COOR: 21 22 55 N 000 56 54E
HGT: 15M
ALT ON TOP: 412M
NIGHT LIGHTED ONLY.

B0221/17 A)DAOY B)1702281459 C)PERM
E)READ FREQ 118.7MHZ(S) INSTEAD OF 118.9MHZ(S)
REF AIP ALGERIA PAGE AD2 DAOY-6 ITEM DAOY AD2.18

B0224/17 A)DAOR B)1703010729 C)1706010800 EST
E)TWY (GOLF) EDGE LGT UNSERVICEABLE
EXC PART BETWEEN TWY (ECHO) AND (FOXTROT)

B0227/17 A)DAOV B)1703020615 C)1706020830 EST
E)SSLI RECLASSE A LA CAT 5

B0230/17 A)DAAS B)1703020618 C)1704030733 EST
E)FIRE FIGHTING AND RESCUE UPGRADED TO CAT 7

B0234/17 A)DATM B)1703021800 C)1704021805 EST
E)NEW DECLARED DISTANCES AVBL:
TORA TODA ASDA LDA
RWY 08: 2700M 2700M 2700M 2700M
RWY 26: 2700M 2700M 2800M 2700M

B0235/17 A)DAUE B)1703021801 C)1704021810 EST
E)SWY RWY 10 UNSERVICEABLE
NEW DECLARED DISTANCES:
RWY 10 :TORA TODA ASDA LDA
1800 1800 1800 1800

B0236/17 A)DAOV B)1703021803 C)1704021815 EST
E)WINDSOCK NOT LGT AT NIGHT

B0238/17 A)DAAE B)1703050626 C)1704060630 EST
E)WIP AT 140M RIGHT SIDE OF RCL 08

B0240/17 A)DAUE B)1703051735 C)1704051800 EST
E)WIND DIRECTION NOT AVBL

B0244/17 A)DAOY B)1703070710 C)1704080708 EST
E)600M FROM THR 22 NOT AVBL DUE TO WIP
NEW DECLARED DISTANCES :
RWY04/22 :TORA=TODA=ASDA=LDA=2400M

B0245/17 A)DAAP B)1703070711 C)1704080709 EST
E)WIND DIRECTION AND VELOCITY DATA NOT AVBL

B0248/17 A)DAOY B)1703080752 C)1704080800 EST
E)INSTANTANEOUS DATA OF WIND DIRECTION AND VELOCITY NOT AVBL

B0250/17 A)DAUE B)1703090610 C)1704090648 EST
E)TWY B1 EDGE LIGHTS U/S

B0251/17 A)DAOY B)1703090623 C)1704090622 EST
E)SWY RWY 04 AND SWY RWY 22 CLSD

B0252/17 A)DAUT B)1703090623 C)1704090623 EST
E)PAPI RWY 24 U/S

B0253/17 A)DAUB B)1703090624 C)1704090623 EST
E)LLZ31/ILS BI FREQ 110.9MHZ U/S

B0255/17 A)DAUB B)1703100812 C)1706090700 EST
E)NEW DECLARED DISTANCES:
TORA TODA ASDA LDA
RWY 13 : 2900 2900 3100 2700
RWY 31 : 2900 2900 2900 2900

B0256/17 A)DAUB B)1703100815 C)1704090900 EST
E)PAPI RWY 13 U/S DUE TO WIP.

B0258/17 A)DAAE B)1703120620 C)1706100730 EST
E)PRESENCE D'OBST CONSTITUE PAR GRUE
PSN: 364414N 0050443E
QDR/DIST QFU08 :033DEG/3556M
HGT: 91.60 M
ALT ON TOP:98.60 M
BALISE JOUR ET NUIT

B0259/17 A)DAAS B)1703120621 C)1704110720 EST
E)CAUSE TRAVAUX
LARGEUR DE BANDE DE PISTE:
LES PREMIERES 2400M RWY 09 EST DE 300M
LES DERNIERES 500M RWY 09 EST DE 210M

B0261/17 A)DAUO B)1703130749 C)1704130800 EST
E)WIP ON MOV AREA .MEN AND ENGINES PRESENCE

B0263/17 A)DAAJ B)1703140602 C)1704150730 EST
E)SWY RWY 13 CLSD

B0264/17 A)DAUE B)1703140604 C)1704160700 EST
E)LGT PRKG AREA U/S

B0265/17 A)DAUO B)1703142016 C)1706151900 EST
E)WIP ON STRIP RWY 13/31. MEN AND EQPT PRESENCE

B0266/17 A)DAUB B)1703142017 C)1706151900 EST
E)GP RWY31 FREQ 330.8 MHZ U/S DUE TO MAINT

B0267/17 A)DAUB B)1703150717 C)1704160800 EST
E) INSTALLATION D'UNE CENTRALE A BETON DE (02) DEUX SILOS.
-HAUTEUR HORS SOL:25M.
-ALTITUDE 77M.
PSN:344738N 0054339E
BALISE DE JOUR SEULEMENT.

B0268/17 A)DAOI B)1703150720 C)1704150830 EST
E)WIP (PRKG EXTENSION) AT 250M THR 08 LEFT SIDE RWY 08/26.

B0273/17 A)DAOV B)1703160626 C)1704160750 EST

E)WIND DIRECTION AND VELOCITY NOT AVBL

B0275/17 A)DAAV B)1703170635 C)1704170635 EST
E)PAPI RWY 17 U/S

B0276/17 A)DAAD B)1703190603 C)1704190800 EST
E)WIP (CONSTRUCTION OF A TEMPORARY CLOSURE SHEET)
MEN AND ENGINES PRESENCE.

B0278/17 A)DAOR B)1703201749 C)1704201730 EST
E)LGT TWY H U/S

B0279/17 A)DAAS B)1703210719 C)1704200800 EST
E)WIP ON RWY 09/27 STRIP

B0280/17 A)DAOF B)1703210723 C)1704220800 EST
E)WIP ON RWY 08L.MEN AND EQPT PRESENCE

B0281/17 A)DAUK B)1703211530 C)1704211530
E)DOGS PRESENCE ON MOV AREA

B0282/17 A)DAOR B)1703211840 C)1704101800 EST
E)GP 18 FREQ 334.7 MHZ U/S

B0284/17 A)DAUI B)1703220641 C)1706220800 EST
E)WIP (CLOSURE) AROUND AD. MEN AND EQPT PRESENCE

B0285/17 A)DATM B)1703220643 C)1706220900 EST
E)WIND DIRECTION AND VELOCITY INFO NOT AVBL

B0288/17 A)DAOI B)1703221719 C)1704231800 EST
E)NEW TWY CONSTRUCTION LOCATED AT 480M THR 08 LEFT SIDE RWY 08/26
MEN AND EQPT PRESENCE

B0289/17 A)DAAE B)1703221722 C)1704222000 EST
E)DME BJ CH42X OPR WO AUX SUPPLY

B0293/17 A)DAAV B)1703240609 C)1706250630 EST
E)ALS RWY 17 U/S

B0294/17 A)DAOI B)1703240616 C)1706210630 EST
E)FIRE FIGHTING AND RESCUE CHANGED TO CAT 7

B0297/17 A)DAAA B)1703250754 C)1704250730 EST
E)REF DAOF /TINDOUF
EVERY FLIGHT OF MINURSO/U.N OR OPERATING FOR UNITED NATIONS TO
ENTER ALGIERS FIR MUST BE COMPULSORY PROCEED VIA POINT "PK 40"
GEO COORD :2720N00840W FL70.
THE FLW POINTS 2739N00840W AND 2734N00840W ARE COMPLETELY WITHDRAWN

B0298/17 A)DAAD B)1703250826 C)1704250735 EST
E)RWY 04/22 CLSD DUE TO WIP
RMK :HR 0700-1600 RWY 04/22 OPEN ONLY FOR ALGERIAN AIR FORCE ACFT

B0299/17 A)DAOR B)1703250832 C)1704060800 EST
E)TWY K CLSD DUE WIP.

B0302/17 A)DAUE B)1703260728 C)1706260900 EST
E)LGT RWY 10/28 U/S

B0303/17 A)DAUT B)1703260944 C)1704091800 EST
E)WIP (LGT) ON RWY 06/24. MEN AND ENGINES PRESENCE.

B0304/17 A)DAOB B)1703261020 C)1704260800 EST
E)TWO ACFT STANDS IN FRONT OF SIGNAL AREA CLSD

B0305/17 A)DAUT B)1703270749 C)1704270830 EST
E)APPROACH LIGHTING SYSTEM RWY 06 U/S

B0306/17 A)DAUE B)1703270751 C)1704280830 EST
E)TWY B2 EDGE LIGHTS U/S

B0307/17 A)DAAE B)1703270755 C)1704260900 EST
E)WIP (CLOSURE) LEFT SIDE QFU26 MARITIME FRONT DIST 110M FROM RWY
08/26
MEN AND ENGINES PRESENCE
CAUTION ADVISED

B0308/17 A)DAOY B)1703270757 C)1704280900 EST
E)RWY 22 SHOULDERS DAMAGED DUE TO FLOOD

B0309/17 A)DAAP B)1703270843 C)1704150800
E)WIP,INSTALLTION OF ALS RWY 09

B0310/17 A)DAAP B)1703270937 C)1704270800 EST
E)SWY RWY 27 UNSERVICEABLE

B0311/17 A)DAAP B)1703270941 C)1704270800 EST
E)NEW DECLARED DISTANCES:
RWY09 TORA 3000 TODA 3000 ASDA 3100 LDA 3000
RWY27 TORA 3000 TODA 3000 ASDA 3000 LDA 3000

B0313/17 A)DAOF B)1703280738 C)1704280900 EST
E)WIP ON RIGHT SIDE OF RWY 26R MEN AND EQPT PRESENCE

B0314/17 A)DAUE B)1703280742 C)1704281000 EST
E)ALL LGT RWY 18/36 U/S

B0315/17 A)DATM B)1703280824 C)1704270800
E)DOGS PRESENCE ON AD

B0317/17 A)DAOR B)1703290600 C)1704150800 EST
E)WIP (RUBBER REMOVAL AND PAINTING) ON MOV AREA
MEN AND EQPT PRESENCE.

B0322/17 A)DAUT B)1703300800 C)1704131800 EST
E)ALL LGT RWY 06/24 U/S

B0325/17 A)DATM B)1703310742 C)1704300646 EST
E)VDF (BORDJ MOKHTAR GONIO) 119.7MHZ AND 118.3MHZ(S) U/S

B0326/17 A)DAOF B)1703310749 C)1704300726 EST
E)ANEMOMETER U/S

B0327/17 A)DATM B)1703311746 C)1704301800 EST
E)FIRST 300M FROM THR 26 NOT AVBL DUE TO WIP
MEN AND EQPT PRESENCE

SERIES B

CHECKLIST

YEAR=2017 0103 0106 0148 0149 0189 0200 0221 0224 0227 0230
0234 0235 0236 0238 0240 0244 0245 0248 0250 0251
0252 0253 0255 0256 0258 0259 0261 0263 0264 0265
0266 0267 0268 0273 0275 0276 0278 0279 0280 0281
0282 0284 0285 0288 0289 0293 0294 0297 0298 0299
0302 0303 0304 0305 0306 0307 0308 0309 0310 0311
0313 0314 0315 0317 0322 0325 0326 0327

CHECKLIST OF AIP SUPPLEMENT IN FORCE
THE FOLLOWING AIP SUPPLEMENT WERE STILL IN FORCE AT 0010 ON 01 APR 17

2016: 001 002 003
LATEST PUBLICATIONS AT 0010 ON 01 APR 17

AIP SUPPLEMENT 003 30 AUG 16
AIP AMENDMENT 001 19 JAN 17
AIRAC AIP AMENDMENT ... 001 26 NOV 15 EFFECTIVE 07 JAN 16
AIC INTERNATIONAL 0002 20 DEC 16
AIC NATIONAL
AIRAC PUBLICATION EFFECTIVE 27 APR 17 - NIL