

PHONE:+213 21 67 96 46
FAX :+213 21 65 63 65
AFTN :DAAAYNYX
WEB : www.sia-enna.dz

ALGERIA
E.N.N. A
AERONAUTICAL INFORMATION SERVICE
ROUTE DE CHERARBA BP 70D ALGER

NOTAM SUMMARY
SERIE B
01 JUL 17

SUMMARY OF NOTAM IN FORCE

THE FOLLOWING NOTAM WERE STILL IN FORCE AT 0025 ON 01 JUL 17,
NOTAM NOT INCLUDED HAVE EITHER BEEN CANCELLED OR SUPERSEDED
BY AIP SUPPLEMENT OR INCORPORATED IN THE AIP ALGERIA.

SERIES B

B0344/17 A)DAUE B)1704080612 C)1707121000 EST
E)TWY B1 EDGE LIGHTS U/S

B0345/17 A)DAUT B)1704080613 C)1707090623 EST
E)PAPI RWY 24 U/S

B0346/17 A)DAOY B)1704080613 C)1707091000 EST
E)SWY RWY 04 AND SWY RWY 22 CLSD

B0347/17 A)DAUB B)1704080614 C)1707090623 EST
E)LLZ31/ILS BI FREQ 110.9MHZ U/S

B0348/17 A)DAUB B)1704080614 C)1707090900 EST
E)PAPI RWY 13 U/S DUE TO WIP.

B0382/17 A)DAAV B)1704160629 C)1707160830 EST
E)PAPI RWY 17 U/S

B0388/17 A)DAAD B)1704180743 C)1707190800 EST
E)WIP (CONSTRUCTION OF A TEMPORARY CLOSURE SHEET)
MEN AND ENGINES PRESENCE.

B0401/17 A)DAAP B)1704210906 C)1707150800 EST
E)TWY B CLSD

B0403/17 A)DAOF B)1704210909 C)1707150800 EST
E)WIP ON RWY 08L,MEN AND EQPT PRESENCE

B0443/17 A)DAUE B)1705031331 C)1708041600 EST
E)WIND DIRECTION NOT AVBL

B0454/17 A)DAAS B)1705081719 C)1707300720 EST
E)CAUSE TRAVAUX
LARGEUR DE BANDE DE PISTE:
LES PREMIERES 2400M RWY 09 EST DE 300M
LES DERNIERES 500M RWY 09 EST DE 210M

B0463/17 A)DAUO B)1705110703 C)1707110800 EST
E)WIP ON MOV AREA .MEN AND ENGINES PRESENCE

B0469/17 A)DAAS B)1705141002 C)PERM
E)IAP ON IAC3 AND IAC4 COMPLETELY WITHDRAWN
REF ALGERIAN AIP PAGE :
AD2 DAAS-IAC3 AND AD2 DAAS-IAC4

B0478/17 A)DAOR B)1705181717 C)1707200800 EST
E)LGT TWY H U/S

B0497/17 A)DAUE B)1705260713 C)1707300800 EST
E)TWY B2 EDGE LIGHTS U/S

B0498/17 A)DAOF B)1705260714 C)1707300800 EST
E)WIP ON RIGHT SIDE OF RWY 26R MEN AND EQPT PRESENCE

B0499/17 A)DAUE B)1705260714 C)1707300800 EST
E)ALL LGT RWY 18/36 U/S

B0507/17 A)DAOR B)1705310629 C)1708250800 EST
E)TWY (GOLF) EDGE LGT UNSERVICEABLE
EXC PART BETWEEN TWY (ECHO) AND (FOXTROT)

B0508/17 A)DAUE B)1705310630 C)1708250900 EST
E)WANDERING DOGS ON AD

B0512/17 A)DAOY B)1705311347 C)1708282359 EST
E)600M FROM THR 04 NOT AVBL DUE TO WIP
NEW DECLARED DISTANCES :
RWY 04/22: TORA=TODA=ASDA=LDA=2400M

B0514/17 A)DAOY B)1705311351 C)1708282359 EST
E)LGT RWY 04/22 AVBL ONLY ON 2400M FROM THR 22

B0521/17 A)DAOV B)1706011739 C)1707021800 EST
E)WINDSOCK NOT LGT AT NIGHT

B0524/17 A)DAAE B)1706030830 C)1707030830 EST
E)WIP AT 140M RIGHT SIDE OF RCL 08

B0525/17 A)DAOY B)1706040718 C)1707040700 EST
E)INSTANTANEOUS DATA OF WIND DIRECTION AND VELOCITY NOT AVBL

B0528/17 A)DAUB B)1706060627 C)1708060630 EST
E)THR RWY 13 DISPLACED 200M DUE TO WIP

B0529/17 A)DAAP B)1706060655 C)1707060700 EST
E)WIND DIRECTION AND VELOCITY DATA NOT AVBL

B0530/17 A)DAUB B)1706080613 C)1709050700 EST
E)NEW DECLARED DISTANCES:
TORA TODA ASDA LDA
RWY 13 : 2900 2900 3100 2700
RWY 31 : 2900 2900 2900 2900

B0532/17 A)DAAE B)1706090806 C)1709080730 EST
E)PRESENCE D'OBST CONSTITUE PAR GRUE
PSN: 364414N 0050443E
QDR/DIST QFU08 :033DEG/3556M
HGT: 91.60 M
ALT ON TOP:98.60 M
BALISE JOUR ET NUIT

B0533/17 A)DAUT B)1706090808 C)1708090705 EST
E)WIP (LGT) ON RWY 06/24. MEN AND ENGINES PRESENCE.

B0534/17 A)DAAJ B)1706090813 C)1707080715 EST
E)SSLI DOWNGRADED TO CAT 7

B0537/17 A)DAOR B)1706111200 C)1707111400 EST
E)LLZ18 BC FREQ 108.1 MHZ U/S DUE TO MAINT.

B0539/17 A)DAUE B)1706130617 C)1707130616 EST
E)LGT PRKG AREA U/S

B0540/17 A)DAAJ B)1706130802 C)1707160801 EST
E)SWY RWY 13 CLSD

B0541/17 A)DAOI B)1706130840 C)1707130839 EST
E)WIP (PRKG EXTENSION) AT 250M THR 08 LEFT SIDE RWY 08/26.

B0542/17 A)DAOV B)1706140717 C)1707170750 EST
E)WIND DIRECTION AND VELOCITY NOT AVBL

B0543/17 A)DAOF B)1706140719 C)1707140800 EST
E)LA BOUCHE D'AVITAILLEMENT DU POSTE N02 N03 N04 EN SEVICE SAUF
LA BOUCHE DU POSTE N01 U/S

B0547/17 A)DAUO B)1706141845 C)1709151900 EST
E)WIP ON STRIP RWY 13/31. MEN AND EQPT PRESENCE

B0548/17 A)DAUB B)1706141846 C)1709151900 EST
E)GP RWY31 FREQ 330.8 MHZ U/S DUE TO MAINT

B0551/17 A)DAUB B)1706160606 C)1707160800 EST
E) INSTALLATION D'UNE CENTRALE A BETON DE (02) DEUX SILOS.
-HAUTEUR HORS SOL:25M.
-ALTITUDE 77M.
PSN:344738N 0054339E
BALISE DE JOUR SEULEMENT.

B0552/17 A)DAAS B)1706180612 C)1707170900 EST
E)WIP ON RWY 09/27 STRIP

B0554/17 A)DAOI B)1706200626 C)1709170630 EST
E)FIRE FIGHTING AND RESCUE CHANGED TO CAT 7

B0557/17 A)DAAE B)1706201719 C)1707201800 EST
E)DME BJ CH42X OPR WO AUX SUPPLY

B0558/17 A)DAOI B)1706201721 C)1707201730 EST
E)NEW TWY CONSTRUCTION LOCATED AT 480M THR 08 LEFT SIDE RWY 08/26
MEN AND EQPT PRESENCE

B0561/17 A)DAUI B)1706210854 C)1709210852 EST
E)WIP (CLOSURE) AROUND AD. MEN AND EQPT PRESENCE

B0562/17 A)DATM B)1706210858 C)1709210900 EST
E)WIND DIRECTION AND VELOCITY INFO NOT AVBL

B0563/17 A)DAUK B)1706210900 C)1707211500 EST
E)STRAY DOGS ON MOV AREA

B0564/17 A)DAAD B)1706220614 C)1707230700 EST
E)RWY 04/22 CLSD DUE TO WIP
RMK :HR 0700-1600 RWY 04/22 OPEN ONLY FOR ALGERIAN AIR FORCE ACFT

B0566/17 A)DAAE B)1706220735 C)1707220900 EST
E)WIP (CLOSURE) LEFT SIDE QFU26 MARITIME FRONT DIST 110M FROM RWY
08/26 MEN AND ENGINES PRESENCE CAUTION ADVISED

B0567/17 A)DAAA B)1706230800 C)1707230800 EST
E)REF DAOF /TINDOUF
EVERY FLIGHT OF MINURSO/U.N OR OPERATING FOR UNITED NATIONS TO
ENTER ALGIERS FIR MUST BE COMPULSORY PROCEED VIA POINT "PK 40"
GEO COORD :2720N00840W FL70.
THE FLW POINTS 2739N00840W AND 2734N00840W ARE COMPLETELY WITHDRAWN

B0568/17 A)DAUT B)1706230831 C)1707230830 EST
E)APPROACH LIGHTING SYSTEM RWY 06 U/S

B0569/17 A)DATM B)1706240720 C)1709210620 EST
E)OBST MAST ERECTED
PSN :900M FROM THR RCL 26
COOR: 21 22 55 N 000 56 54E
HGT: 15M
ALT ON TOP: 412M
NIGHT LIGHTED ONLY.

B0570/17 A)DAAV B)1706240725 C)1709210630 EST
E)ALS RWY 17 U/S

B0571/17 A)DAAP B)1706240731 C)1709220800 EST
E)SWY RWY 27 U/S.

B0572/17 A)DAAP B)1706240735 C)1709220805 EST
E)NEW DECLARED DISTANCES:
RWY09 TORA 3000 TODA 3000 ASDA 3100 LDA 3000
RWY27 TORA 3000 TODA 3000 ASDA 3000 LDA 3000

B0573/17 A)DAOB B)1706240741 C)1709200700 EST
E)TWO ACFT STANDS IN FRONT OF SIGNAL AREA CLSD

B0574/17 A)DAUE B)1706250653 C)1709100900 EST
E)LGT RWY 10/28 U/S

B0575/17 A)DAOY B)1706250656 C)1709100800 EST
E)RWY 22 SHOULDERS DAMAGED DUE TO FLOOD

B0576/17 A)DATM B)1706270742 C)1707270800 EST
E)FIRST 300M FROM THR 26 NOT AVBL DUE TO WIP
MEN AND EQPT PRESENCE

B0578/17 A)DATM B)1706290746 C)1707290745 EST
E)VDF (BORDJ MOKHTAR GONIO) 119.7MHZ AND 118.3MHZ(S) U/S

B0579/17 A)DAOF B)1706290747 C)1707290800 EST
E)ANEMOMETER U/S

B0580/17 A)DAOR B)1706291809 C)1707301000 EST
E)WIP (RUBBER REMOVAL AND PAINTING) ON MOV AREA MEN AND EQPT
PRESENCE.

B0581/17 A)DATM B)1706291811 C)1707301815 EST
E)NEW DECLARED DISTANCES AVBL:
TORA TODA ASDA LDA
RWY 08: 2700M 2700M 2700M 2700M
RWY 26: 2700M 2700M 2800M 2700M

B0582/17 A)DAUE B)1706291813 C)1707301815 EST
E)SWY RWY 10 UNSERVICEABLE
NEW DECLARED DISTANCES:
RWY 10 :TORA TODA ASDA LDA
1800 1800 1800 1800

B0583/17 A)DAOV B)1706300754 C)1707300606 EST
E)SLI RECLASSE A LA CAT 5

B0584/17 A)DAAS B)1706300802 C)1707300617 EST
E)FIRE FIGHTING AND RESCUE UPGRADED TO CAT 7

SERIES B

CHECKLIST

YEAR=2017 0344 0345 0346 0347 0348 0382 0388 0401 0403 0443
0454 0463 0469 0478 0497 0498 0499 0507 0508 0512
0514 0521 0524 0525 0528 0529 0530 0532 0533 0534
0537 0539 0540 0541 0542 0543 0547 0548 0551 0552
0554 0557 0558 0561 0562 0563 0564 0566 0567 0568
0569 0570 0571 0572 0573 0574 0575 0576 0578 0579
0580 0581 0582 0583 0584

CHECKLIST OF AIP SUPPLEMENT IN FORCE
THE FOLLOWING AIP SUPPLEMENT WERE STILL IN FORCE AT 0025 ON 01 JUL 17

2016: 001
LATEST PUBLICATIONS AT 0025 ON 01 JUL 17

AIP SUPPLEMENT 003 30 SEP 16
AIP AMENDMENT 003 11 MAY 17

AIRAC AIP AMENDMENT ... 001 26 NOV 15 EFFECTIVE 07 JAN 16
AIC INTERNATIONAL 0002 20 DEC 16
AIC NATIONAL
AIRAC PUBLICATION EFFECTIVE 20 JUL 17 - NIL