

PHONE:+213 21 67 96 46
FAX :+213 21 65 63 65
AFTN :DAAAYNYX
WEB : www.sia-enna.dz

ALGERIA
E.N.N. A
AERONAUTICAL INFORMATION SERVICE
ROUTE DE CHERARBA BP 70D ALGER

NOTAM SUMMARY
SERIE B
01 JUN 17

SUMMARY OF NOTAM IN FORCE

THE FOLLOWING NOTAM WERE STILL IN FORCE AT 0025 ON 01 JUN 17,
NOTAM NOT INCLUDED HAVE EITHER BEEN CANCELLED OR SUPERSEDED
BY AIP SUPPLEMENT OR INCORPORATED IN THE AIP ALGERIA.

SERIES B

B0227/17 A)DAOV B)1703020615 C)1706020830 EST
E)SSLI RECLASSE A LA CAT 5

B0255/17 A)DAUB B)1703100812 C)1706090700 EST
E)NEW DECLARED DISTANCES:

TORA TODA ASDA LDA
RWY 13 : 2900 2900 3100 2700
RWY 31 : 2900 2900 2900 2900

B0258/17 A)DAAE B)1703120620 C)1706100730 EST
E)PRESENCE D'OBST CONSTITUE PAR GRUE

PSN: 364414N 0050443E
QDR/DIST QFU08 :033DEG/3556M
HGT: 91.60 M
ALT ON TOP:98.60 M
BALISE JOUR ET NUIT

B0265/17 A)DAUO B)1703142016 C)1706151900 EST
E)WIP ON STRIP RWY 13/31. MEN AND EQPT PRESENCE

B0266/17 A)DAUB B)1703142017 C)1706151900 EST
E)GP RWY31 FREQ 330.8 MHZ U/S DUE TO MAINT

B0284/17 A)DAUI B)1703220641 C)1706220800 EST
E)WIP (CLOSURE) AROUND AD. MEN AND EQPT PRESENCE

B0285/17 A)DATM B)1703220643 C)1706220900 EST
E)WIND DIRECTION AND VELOCITY INFO NOT AVBL

B0293/17 A)DAAV B)1703240609 C)1706250630 EST
E)ALS RWY 17 U/S

B0294/17 A)DAOI B)1703240616 C)1706210630 EST
E)FIRE FIGHTING AND RESCUE CHANGED TO CAT 7

B0302/17 A)DAUE B)1703260728 C)1706260900 EST
E)LGT RWY 10/28 U/S

B0340/17 A)DAUB B)1704070629 C)1706070630 EST
E)THR RWY 13 DISPLACED 200M DUE TO WIP

B0344/17 A)DAUE B)1704080612 C)1707121000 EST
E)TWY B1 EDGE LIGHTS U/S

B0345/17 A)DAUT B)1704080613 C)1707090623 EST
E)PAPI RWY 24 U/S

B0346/17 A)DAOY B)1704080613 C)1707091000 EST
E)SWY RWY 04 AND SWY RWY 22 CLSD

B0347/17 A)DAUB B)1704080614 C)1707090623 EST
E)LLZ31/ILS BI FREQ 110.9MHZ U/S

B0348/17 A)DAUB B)1704080614 C)1707090900 EST
E)PAPI RWY 13 U/S DUE TO WIP.

B0349/17 A)DAUT B)1704081721 C)1706100700 EST
E)WIP (LGT) ON RWY 06/24. MEN AND ENGINES PRESENCE.

B0372/17 A)DAAJ B)1704140800 C)1706140800 EST
E)SWY RWY 13 CLSD

B0382/17 A)DAAV B)1704160629 C)1707160830 EST
E)PAPI RWY 17 U/S

B0388/17 A)DAAD B)1704180743 C)1707190800 EST
E)WIP (CONSTRUCTION OF A TEMPORARY CLOSURE SHEET)
MEN AND ENGINES PRESENCE.

B0401/17 A)DAAP B)1704210906 C)1707150800 EST
E)TWY B CLSD

B0403/17 A)DAOF B)1704210909 C)1707150800 EST
E)WIP ON RWY 08L,MEN AND EQPT PRESENCE

B0410/17 A)DATM B)1704240602 C)1706250620 EST
E)OBST MAST ERECTED
PSN :900M FROM THR RCL 26
COOR: 21 22 55 N 000 56 54E
HGT: 15M
ALT ON TOP: 412M
NIGHT LIGHTED ONLY.

B0437/17 A)DAAS B)1705010621 C)1706020733 EST
E)FIRE FIGHTING AND RESCUE UPGRADED TO CAT 7

B0441/17 A)DAOV B)1705021800 C)1706021800 EST
E)WINDSOCK NOT LGT AT NIGHT

B0443/17 A)DAUE B)1705031331 C)1708041600 EST
E)WIND DIRECTION NOT AVBL

B0445/17 A)DAAE B)1705040802 C)1706040800 EST
E)WIP AT 140M RIGHT SIDE OF RCL 08

B0450/17 A)DAAP B)1705060734 C)1706070700 EST
E)WIND DIRECTION AND VELOCITY DATA NOT AVBL

B0451/17 A)DAOY B)1705060735 C)1706050700 EST
E)INSTANTANEOUS DATA OF WIND DIRECTION AND VELOCITY NOT AVBL

B0454/17 A)DAAS B)1705081719 C)1707300720 EST
E)CAUSE TRAVAUX
LARGEUR DE BANDE DE PISTE:
LES PREMIERES 2400M RWY 09 EST DE 300M
LES DERNIERES 500M RWY 09 EST DE 210M

B0457/17 A)DAOI B)1705091131 C)1706091600
E)WIP BEFORE THR 26, AT 50 M OF EXTENDED CENTERLINE
MEN AND EQPT PRESENCE

B0460/17 A)DAAS B)1705110001 C)1706112359
E)IAP ON IAC1 AND IAC2 HAVE BEEN REPLACED BY NEW IAP DUE TO CHANGE OF
STF VOR/DME COORDINATES.
REF:AMDT 03/17 AVAILABLE ON ALGERIAN AIS WEB SITE
WWW.SIA-ENNA.DZ

B0463/17 A)DAUO B)1705110703 C)1707110800 EST
E)WIP ON MOV AREA .MEN AND ENGINES PRESENCE

B0465/17 A)DAAJ B)1705131820 C)1706100700 EST
E)SSLI DOWNGRADED TO CAT 7

B0466/17 A)DAUE B)1705140652 C)1706140700 EST
E)LGT PRKG AREA U/S

B0467/17 A)DAUB B)1705140657 C)1706170800 EST
E) INSTALLATION D'UNE CENTRALE A BETON DE (02) DEUX SILOS.
-HAUTEUR HORS SOL:25M.
-ALTITUDE 77M.
PSN:344738N 0054339E
BALISE DE JOUR SEULEMENT.

B0468/17 A)DAOI B)1705140658 C)1706140835 EST
E)WIP (PRKG EXTENSION) AT 250M THR 08 LEFT SIDE RWY 08/26.

B0469/17 A)DAAS B)1705141002 C)PERM
E)JAP ON IAC3 AND IAC4 COMPLETELY WITHDRAWN
REF ALGERIAN AIP PAGE :
AD2 DAAS-IAC3 AND AD2 DAAS-IAC4

B0470/17 A)DAOV B)1705150612 C)1706150750 EST
E)WIND DIRECTION AND VELOCITY NOT AVBL

B0471/17 A)DAOF B)1705150613 C)1706150800 EST
E)LA BOUCHE D'AVITAILLEMENT DU POSTE N02 N03 N04 EN SEVICE SAUF
LA BOUCHE DU POSTE N01 U/S

B0475/17 A)DAAS B)1705180610 C)1706190900 EST
E)WIP ON RWY 09/27 STRIP

B0478/17 A)DAOR B)1705181717 C)1707200800 EST
E)LGT TWY H U/S

B0480/17 A)DAAE B)1705201721 C)1706211800 EST
E)DME BJ CH42X OPR WO AUX SUPPLY

B0482/17 A)DAOI B)1705211724 C)1706211800 EST
E)NEW TWY CONSTRUCTION LOCATED AT 480M THR 08 LEFT SIDE RWY 08/26
MEN AND EQPT PRESENCE

B0483/17 A)DAUK B)1705221448 C)1706221500 EST
E)STRAY DOGS ON MOV AREA

B0484/17 A)DAAD B)1705230630 C)1706230700 EST
E)RWY 04/22 CLSD DUE TO WIP
RMK :HR 0700-1600 RWY 04/22 OPEN ONLY FOR ALGERIAN AIR FORCE ACFT

B0485/17 A)DAAE B)1705230632 C)1706230900 EST
E)WIP (CLOSURE) LEFT SIDE QFU26 MARITIME FRONT DIST 110M FROM RWY
08/26
MEN AND ENGINES PRESENCE
CAUTION ADVISED

B0486/17 A)DAOB B)1705240743 C)1706250800 EST
E)TWO ACFT STANDS IN FRONT OF SIGNAL AREA CLSD

B0493/17 A)DAAA B)1705250702 C)1706240700 EST
E)REF DAOF /TINDOUF
EVERY FLIGHT OF MINURSO/U.N OR OPERATING FOR UNITED NATIONS TO
ENTER ALGIERS FIR MUST BE COMPULSORY PROCEED VIA POINT "PK 40"
GEO COORD :2720N00840W FL70.
THE FLW POINTS 2739N00840W AND 2734N00840W ARE COMPLETELY WITHDRAWN

B0494/17 A)DAUT B)1705250704 C)1706240830 EST
E)APPROACH LIGHTING SYSTEM RWY 06 U/S

B0495/17 A)DAAP B)1705250705 C)1706250800 EST
E)SWY RWY 27 U/S.

B0496/17 A)DAAP B)1705250706 C)1706250800 EST
E)NEW DECLARED DISTANCES:
RWY09 TORA 3000 TODA 3000 ASDA 3100 LDA 3000
RWY27 TORA 3000 TODA 3000 ASDA 3000 LDA 3000

B0497/17 A)DAUE B)1705260713 C)1707300800 EST
E)TWY B2 EDGE LIGHTS U/S

B0498/17 A)DAOF B)1705260714 C)1707300800 EST
E)WIP ON RIGHT SIDE OF RWY 26R MEN AND EQPT PRESENCE

B0499/17 A)DAUE B)1705260714 C)1707300800 EST
E)ALL LGT RWY 18/36 U/S

B0500/17 A)DAOY B)1705260716 C)1706260800 EST
E)RWY 22 SHOULDERS DAMAGED DUE TO FLOOD

B0502/17 A)DATM B)1705280731 C)1706280730 EST
E)FIRST 300M FROM THR 26 NOT AVBL DUE TO WIP
MEN AND EQPT PRESENCE

B0503/17 A)DAOR B)1705281350 C)1706281400 EST
E)LLZ18 BC FREQ 108.1 MHZ ON TEST, DO NOT USE

B0504/17 A)DAOR B)1705290721 C)1706301000 EST
E)WIP (RUBBER REMOVAL AND PAINTING) ON MOV AREA MEN AND EQPT
PRESENCE.

B0505/17 A)DATM B)1705290722 C)1706301200 EST
E)VDF (BORDJ MOKHTAR GONIO) 119.7MHZ AND 118.3MHZ(S) U/S

B0506/17 A)DAOF B)1705290724 C)1706300930 EST
E)ANEMOMETER U/S

B0507/17 A)DAOR B)1705310629 C)1708250800 EST
E)TWY (GOLF) EDGE LGT UNSERVICEABLE
EXC PART BETWEEN TWY (ECHO) AND (FOXTROT)

B0508/17 A)DAUE B)1705310630 C)1708250900 EST
E)WANDERING DOGS ON AD

B0509/17 A)DAUU B)1706011500 C)1706011930
E)SSLI CHANGED TO CAT 9

B0512/17 A)DAOY B)1705311347 C)1708282359 EST
E)600M FROM THR 04 NOT AVBL DUE TO WIP
NEW DECLARED DISTANCES :
RWY 04/22: TORA=TODA=ASDA=LDA=2400M

B0514/17 A)DAOY B)1705311351 C)1708282359 EST
E)LGT RWY 04/22 AVBL ONLY ON 2400M FROM THR 22

B0515/17 A)DATM B)1705311730 C)1706301800 EST
E)NEW DECLARED DISTANCES AVBL:
TORA TODA ASDA LDA
RWY 08: 2700M 2700M 2700M 2700M
RWY 26: 2700M 2700M 2800M 2700M

B0516/17 A)DAUE B)1705311732 C)1706301805 EST
E)SWY RWY 10 UNSERVICEABLE
NEW DECLARED DISTANCES:
RWY 10 :TORA TODA ASDA LDA
1800 1800 1800 1800

SERIES B

CHECKLIST

YEAR=2017 0227 0255 0258 0265 0266 0284 0285 0293 0294 0302

0340 0344 0345 0346 0347 0348 0349 0372 0382 0388

0401 0403 0410 0437 0441 0443 0445 0450 0451 0454

0457 0460 0463 0465 0466 0467 0468 0469 0470 0471

0475 0478 0480 0482 0483 0484 0485 0486 0493 0494

0495 0496 0497 0498 0499 0500 0502 0503 0504 0505

0506 0507 0508 0509 0512 0514 0515 0516

CHECKLIST OF AIP SUPPLEMENT IN FORCE

THE FOLLOWING AIP SUPPLEMENT WERE STILL IN FORCE AT 0025 ON 01 JUN 17

2016: 001

LATEST PUBLICATIONS AT 0025 ON 01 JUN 17

AIP SUPPLEMENT 003 30 SEP 16

AIP AMENDMENT 003 11 MAY 17

AIRAC AIP AMENDMENT ... 001 26 NOV 15 EFFECTIVE 07 JAN 16

AIC INTERNATIONAL 0002 20 DEC 16

AIC NATIONAL

AIRAC PUBLICATION EFFECTIVE 22 JUN 17 - NIL