

PHONE:+213 21 67 96 46
FAX :+213 21 65 63 65
AFTN :DAAAYNYX
WEB : www.sia-enna.dz

ALGERIA
E.N.N. A
AERONAUTICAL INFORMATION SERVICE
ROUTE DE CHERARBA BP 70D ALGER

NOTAM SUMMARY
SERIE B
01 NOV 17

SUMMARY OF NOTAM IN FORCE

THE FOLLOWING NOTAM WERE STILL IN FORCE AT 0020 ON 01 NOV 17,
NOTAM NOT INCLUDED HAVE EITHER BEEN CANCELLED OR SUPERSEDED
BY AIP SUPPLEMENT OR INCORPORATED IN THE AIP ALGERIA.

SERIES B

B0731/17 A)DAOY B)1708272247 C)1711272359 EST
E)600M FROM THR 04 NOT AVBL DUE TO WIP
NEW DECLARED DISTANCES :
RWY 04/22: TORA=TODA=ASDA=LDA=2400M

B0732/17 A)DAOY B)1708272249 C)1711272359 EST
E)LGT RWY 04/22 AVBL ONLY ON 2400M FROM THR 22

B0750/17 A)DAUB B)1709040616 C)1712010700 EST
E)NEW DECLARED DISTANCES:
TORA TODA ASDA LDA
RWY 13 : 2900 2900 3100 2700
RWY 31 : 2900 2900 2900 2900

B0757/17 A)DAUO B)1709060716 C)1711060800 EST
E)WIP ON MOV AREA .MEN AND EQPT PRESENCE

B0765/17 A)DAUE B)1709090755 C)1712090900 EST
E)LGT RWY 10/28 U/S

B0766/17 A)DAOY B)1709090801 C)1712090800 EST
E)RWY 22 SHOULDERS DAMAGED DUE TO FLOOD

B0769/17 A)DAOF B)1709120725 C)1712120800 EST
E)LA BOUCHE D'AVITAILLEMENT DU POSTE N02 N03 N04 EN SEVICE SAUF
LA BOUCHE DU POSTE N01 U/S

B0779/17 A)DAUO B)1709141858 C)1712122000 EST
E)WIP ON STRIP RWY 13/31. MEN AND EQPT PRESENCE

B0780/17 A)DAUB B)1709142010 C)1711202100 EST
E)GP RWY31 FREQ 330.8 MHZ U/S DUE TO MAINT

B0783/17 A)DAOI B)1709160830 C)1712160830 EST
E)FIRE FIGHTING AND RESCUE CHANGED TO CAT 7

B0786/17 A)DAOY B)1709171018 C)PERM
E)-LIRE TEL TWR/BIA:(049)612731 AU LIEU DE (049)612732
-BUREAU DE PISTE MET: LIRE H24 AU LIEU DE :PRESENCE PENDANT
LES HEURES DE VOL.
-HEURES DE SERVICES CENTRE METEOROLOGIQUE RESPONSABLE EN DEHORS DE
CES HEURES:LIRE H24 AU LIEU DE NEANT.
AMENDEZ PAGE AIP ALGERIE: AD2 DAOY-1 ET AD2 DAOY-4

B0788/17 A)DAOB B)1709180815 C)PERM
E)REF PAGE AD2 DAOB-6
REF DAOB REF AD 2.18
LIRE LES HEURS DE FONCTIONNEMENT:
0600/1800 AU LIEU DE 0700/1500
REF AMDT AIRAC NR 02/17

B0790/17 A)DAUK B)1709191402 C)1711191500 EST
E)STRAY DOGS ON MOV AREA

B0791/17 A)DAAE B)1709191754 C)1712181800 EST
E)DME BJ CH42X OPR WO AUX SUPPLY

B0792/17 A)DAUI B)1709200629 C)1712180852 EST
E)WIP (CLOSURE) AROUND AD. MEN AND EQPT PRESENCE

B0793/17 A)DATM B)1709200630 C)1712180900 EST
E)WIND DIRECTION AND VELOCITY INFO NOT AVBL

B0794/17 A)DATM B)1709200631 C)1712180620 EST
E)OBST MAST ERECTED
PSN :900M FROM THR RCL 26
COOR: 21 22 55 N 000 56 54E
HGT: 15M
ALT ON TOP: 412M
NIGHT LIGHTED ONLY.

B0795/17 A)DAAV B)1709200632 C)1712190630 EST
E)ALS RWY 17 U/S

B0800/17 A)DAOB B)1709201039 C)PERM
E)-LIRE: (1)EN DEHORS DE CES HEURES UN PN AVANT 1300 ADRESSE A
DAOBYDYD
AU LIEU DE: (1) UN PN AVANT 1300 ADRESSE A DAOBYDYD POUR LES VOLS
NON
REGULIERS.
-REF AIP PAGE AD 2 DAOB-1
DAOB AD 2.3 HEURES FONCTIONNEMENT
LIGNE 12- OBSERVATIONS

B0804/17 A)DAAP B)1709210647 C)1712210800 EST
E)SWY RWY 27 U/S.

B0805/17 A)DAAP B)1709210649 C)1712220805 EST
E)NEW DECLARED DISTANCES:
RWY09 TORA 3000 TODA 3000 ASDA 3100 LDA 3000
RWY27 TORA 3000 TODA 3000 ASDA 3000 LDA 3000

B0810/17 A)DAUE B)1709240627 C)1711230900 EST
E)WANDERING DOGS ON AD

B0834/17 A)DAOI B)1710030646 C)1711030800 EST
E)WIP BEFORE THR 26, AT 50 M OF EXTENDED CENTERLINE
MEN AND EQPT PRESENCE

B0835/17 A)DAAP B)1710030647 C)1711030800 EST
E)WIND DIRECTION AND VELOCITY DATA NOT AVBL

B0837/17 A)DAOR B)1710031000 C)1711031000 EST
E)LLZ RWY18 BC FREQ 108.1MHZ ON TEST,DO NOT USE

B0839/17 A)DAUB B)1710040612 C)1712040630 EST
E)THR RWY 13 DISPLACED 200M DUE TO WIP

B0841/17 A)DAOY B)1710050741 C)1711060800 EST
E)SWY RWY 04 AND SWY RWY 22 CLSD

B0842/17 A)DAUT B)1710050742 C)1711060745 EST
E)PAPI RWY 24 U/S

B0843/17 A)DAAJ B)1710050743 C)1711060830 EST
E)SSLI DOWNGRADED TO CAT 7

B0844/17 A)DAUB B)1710050744 C)1711060845 EST
E)LLZ31/ILS BI FREQ 110.9MHZ U/S

B0845/17 A)DAUB B)1710050745 C)1711060900 EST
E)PAPI RWY 13 U/S DUE TO WIP.

B0846/17 A)DAAE B)1710060901 C)1711060900 EST
E)PRESENCE D'OBST CONSTITUE PAR GRUE
PSN: 364414N 0050443E
QDR/DIST QFU08 :033DEG/3556M
HGT: 91.60 M
ALT ON TOP:98.60 M
BALISE JOUR ET NUIT

B0847/17 A)DAUE B)1710060930 C)1711060930 EST
E)TWY B1 EDGE LIGHTS U/S

B0851/17 A)DAAP B)1710081036 C)1711072359
E)WANDERING DOGS PRESENCE ON AD

B0852/17 A)DAOI B)1710090837 C)1711090830 EST
E)WIP (PRKG EXTENSION) AT 250M THR 08 LEFT SIDE RWY 08/26.

B0854/17 A)DAAP B)1710110754 C)1801110700 EST
E)TWY B CLSD

B0855/17 A)DAOF B)1710110800 C)1801110815 EST
E)WIP ON RWY 08L, MEN AND EQPT PRESENCE

B0856/17 A)DAAV B)1710110802 C)1801110820 EST
E)PAPI RWY 17 U/S

B0857/17 A)DAAJ B)1710110805 C)1711120800 EST
E)SWY RWY 13 CLSD

B0858/17 A)DAUB B)1710110807 C)1711110800 EST
E) INSTALLATION D'UNE CENTRALE A BETON DE (02) DEUX SILOS.
-HAUTEUR HORS SOL:25M.
-ALTITUDE 77M.
PSN:344738N 0054339E
BALISE DE JOUR SEULEMENT.

B0859/17 A)DAOV B)1710110808 C)1711110830 EST
E)WIND DIRECTION AND VELOCITY NOT AVBL

B0860/17 A)DAAS B)1710110809 C)1711110730 EST
E)WIP ON RWY 09/27 STRIP

B0861/17 A)DAUT B)1710132006 C)1711131800 EST
E)WIND DIRECTION AND VELOCITY INFO NOT AVBL

B0862/17 A)DAAD B)1710140701 C)1712150800 EST
E)WIP (CONSTRUCTION OF A TEMPORARY CLOSURE SHEET)
MEN AND ENGINES PRESENCE.

B0865/17 A)DAUI B)1710151017 C)1711101100
E)WIP ON RWY 05/23 PRESENCE .MEN AND EQPT

B0867/17 A)DAUE B)1710160700 C)1712310700
D)0700/1500
E)WIP ON RWY 10/28 EDGES .MEN AND ENGINES PRESENCE

B0869/17 A)DAUK B)1710171509 C)PERM
E)READ:
- FAF 5,14NM DME TGU INSTEAD OF FAF 5NM DME TGU.
- DESCENT GRADIENT 5,8 PERCENT INSTEAD OF 5,4 PERCENT.
REF AIP PAGE : AD2-DAUK IAC1 , AD2-DAUK IAC2.

B0872/17 A)DAOR B)1710180917 C)1801150707 EST
E)LGT TWY H U/S

B0873/17 A)DAAE B)1710180918 C)1711170830 EST
E)WIP (CLOSURE) LEFT SIDE QFU26 MARITIME FRONT DIST 110M FROM RWY
08/26
MEN AND ENGINES PRESENCE
CAUTION ADVISED

B0878/17 A)DAAD B)1710210900 C)1711210900 EST
E)RWY 04/22 CLSD DUE TO WIP
RMK :HR 0700-1600 RWY 04/22 OPEN ONLY FOR ALGERIAN AIR FORCE ACFT

B0879/17 A)DAUT B)1710210947 C)1711210945 EST
E)APPROACH LIGHTING SYSTEM RWY 06 U/S

B0880/17 A)DAAA B)1710211000 C)1711211000 EST
E)REF DAOF /TINDOUF
EVERY FLIGHT OF MINURSO/U.N OR OPERATING FOR UNITED NATIONS TO
ENTER ALGIERS FIR MUST BE COMPULSORY PROCEED VIA POINT "PK 40"
GEO COORD :2720N00840W FL70.
THE FLW POINTS 2739N00840W AND 2734N00840W ARE COMPLETELY WITHDRAWN

B0881/17 A)DAOV B)1710220722 C)1711220730 EST
E)NDB GRS FREQ 424 KHZ U/S

B0882/17 A)DAUK B)1710221042 C)1711221500
E)WIP ON MOV AREA MEN AND EQPT PRESENCE

B0883/17 A)DATM B)1710230658 C)1711240800 EST
E)FIRST 300M FROM THR 26 NOT AVBL DUE TO WIP
MEN AND EQPT PRESENCE

B0886/17 A)DAAS B)1710230836 C)PERM
E)REF AD2 DAAS-AD :
READ RWY09:086 DEG INSTEAD OF RWY09:266 DEG
READ RWY27:266 DEG INSTEAD OF RWY27:086 DEG

B0888/17 A)DATM B)1710240801 C)1711240900 EST
E)VDF (BORDJ MOKHTAR GONIO) 119.7MHZ AND 118.3MHZ(S) U/S

B0889/17 A)DAOR B)1710240806 C)1712240930 EST
E)TWY (GOLF) EDGE LGT UNSERVICEABLE
EXC PART BETWEEN TWY (ECHO) AND (FOXTROT)

B0890/17 A)DAOF B)1710240810 C)1711240930 EST
E)ANEMOMETER U/S

B0896/17 A)DAUE B)1710260828 C)1711260830 EST
E)ALL LGT RWY 18/36 U/S

B0897/17 A)DAOB B)1710260900 C)1711260900 EST
E)MARQUAGE SOL POSTE DE STATIONEMENT P4 ET P5 NON CONFORME
POUR L'AVITAAILLEMENT A/C CAT C-D.

B0899/17 A)DAAE B)1710270720 C)1711270730 EST
E)WIP AT 140M RIGHT SIDE OF RCL 08

B0900/17 A)DAOF B)1710270803 C)1711270800 EST
E)WIP ON RIGHT SIDE OF RWY 26R MEN AND EQPT PRESENCE

B0901/17 A)DAAS B)1710270810 C)1711280815 EST
E)FIRE FIGHTING AND RESCUE UPGRADED TO CAT 7

B0902/17 A)DAOI B)1710271747 C)1711270800 EST
E)NEW TWY CONSTRUCTION LOCATED AT 480M THR 08 LEFT SIDE RWY 08/26
MEN AND EQPT PRESENCE

B0904/17 A)DATM B)1710271750 C)1711270800 EST
E)NEW DECLARED DISTANCES AVBL:
TORA TODA ASDA LDA
RWY 08: 2700M 2700M 2700M 2700M
RWY 26: 2700M 2700M 2800M 2700M

B0905/17 A)DAAS B)1710280631 C)1711270800 EST
E)CAUSE TRAVAUX
LARGEUR DE BANDE DE PISTE:
LES PREMIERES 2400M RWY 09 EST DE 300M
LES DERNIERES 500M RWY 09 EST DE 210M

B0906/17 A)DAUE B)1710280633 C)1711280810 EST
E)TWY B2 EDGE LIGHTS U/S

B0907/17 A)DAUE B)1710281930 C)1711281930 EST
E)SWY RWY 10 UNSERVICEABLE
NEW DECLARED DISTANCES:
RWY 10 :TORA TODA ASDA LDA
1800 1800 1800 1800

B0908/17 A)DAOV B)1710290801 C)1711290800 EST
E)SSLI RECLASSE A LA CAT 5

B0909/17 A)DAUI B)1710300947 C)1711301200
E)OBST (DRILLING MAST) ERECTED :
PSN:271326.93N 0022847.99E
HGT:55M
ALT:337M
DAY MARKED AND NGT LGTD

B0910/17 A)DAAS B)1711021400 C)1711031100
E)RWY 09/27 CLSD.

B0911/17 A)DAOY B)1710310702 C)1801311700 EST
E)INSTANTANEOUS DATA OF WIND DIRECTION AND VELOCITY NOT AVBL

SERIES B

CHECKLIST

YEAR=2017 0731 0732 0750 0757 0765 0766 0769 0779 0780 0783
0786 0788 0790 0791 0792 0793 0794 0795 0800 0804
0805 0810 0834 0835 0837 0839 0841 0842 0843 0844
0845 0846 0847 0851 0852 0854 0855 0856 0857 0858
0859 0860 0861 0862 0865 0867 0869 0872 0873 0878
0879 0880 0881 0882 0883 0886 0888 0889 0890 0896
0897 0899 0900 0901 0902 0904 0905 0906 0907 0908
0909 0910 0911

CHECKLIST OF AIP SUPPLEMENT IN FORCE
THE FOLLOWING AIP SUPPLEMENT WERE STILL IN FORCE AT 0020 ON 01 NOV 17
NONE

LATEST PUBLICATIONS AT 0020 ON 01 NOV 17

AIP SUPPLEMENT 001 20 JUL 17
AIP AMENDMENT 004 15 OCT 17
AIRAC AIP AMENDMENT ... 004 28 SEP 17 EFFECTIVE 09 NOV 17
AIC INTERNATIONAL 0002 20 DEC 16
AIC NATIONAL